



2244 Airport Way, Redmond, Oregon 97756 Phone 541 923-2233 Fax 541 923-2255

SERVICE BULLETIN

SB029-0796

Subject: Lancair IV Air Intake Filter Bypass
Date: 8th July, 1996
Ref: Construction manual, Chapter 31, Section G
Pages: Refer to attached pages
Status: Recommended Modification

Background:

We are recommending a modification be made to the engine air filter bypass. All Lancair IV Customers will receive a revision for the manual that outlines this change. The parts for the recommended modification are available through Lancair at cost.

Note: If you have already installed the alternate air opening and wish to install the filter bypass door, it is not necessary to remove the existing alternate air opening.

Action:

Refer to Revision