



2244 Airport Way, Redmond, Oregon 97756 Phone 541 923-2233 Fax 541 923-2255

SERVICE BULLETIN

SB053-0100

Subject: LANCAIR IV-P Fast Build Engine Options PN# LIVF -FFII

Date: 07 Jan., 2000

Ref: Fig. 1

Pages: 1

Status: Mandatory Inspection

Background:

The Lancair IV-P engine options have four sonic ports mounted on or near the two primary intercooler assemblies. Two of the ports are mounted on the rear of the intercoolers with a short hose and clamps.

Some of the option kits may have been shipped with the arrows on the ports pointing towards the coolers rather than away from the coolers.

Action:

Loosen the clamp on the hose holding each sonic port and remount each port with the arrow pointing away from the cooler, then tighten the clamp.

